RECEIVED

PUGET SOUND AIR POLLUTION CONTROL AGENCY

110 Union Street, Suite 500, Seattle, Washington 98101-2038

NOV 4 1997

Fax: 206-343-7522

AGCW-SEATTLE

Registration No. 11339 Case No		
COMPLIANCE S	STATUS REPORT	
Date of Report October 30	, 19 <u>97</u> atm.	
Source Name	Responsible Person, Title	
Ash Grove Cement Co.	Henrik Voldback	
Location 3801 E. Marginal Way 50.	Seattle, WA. 98134	
No violations of PSAPCA's regulations respect to the areas of the facility I inspected	were observed at the time of my inspection, with ed.	
During my inspection I noted the following	g deficiencies:	
No déficiencies were 1997 CEM report	noted on your September	
that you reported on a	average opacity of 5.2% of 9/8/97 and 9/49/97 and 9/49/97 and 14/9/97 and 14/9/97 and 14/9/97 and 14/9/97 and 14/9/97 arc 11/9 I 9.09 (b)(2) Standard	
Diament within ton	(10) working the standard line of the standard line	
-	Received by	

PUGET SOUND AIR POLLUTION CONTROL AGENCY

110 Union Street, Suite 500, Seattle, Washington 98101-2038

Fax: 206-343-7522

Registration No. 1339	Case No.	1
COMPLIANCE	STATUS REPO	RT
Date of Report Feb 5 ⁺¹	, 19 <u>99</u>	at <u>8:45 4</u> m.
Source Name	Responsible Person, Title	
Ash Grove Cement Co.	Henrik Voldback	Mgr.
Location		
3801 E. Marginal Way		
No violations of PSAPCA's regulations respect to the areas of the facility I inspect	were observed at the time of red.	my inspection, with
During manifestatic Land of the state of the		
During my inspection I noted the following	g deficiencies:	
Regulation T 7.09 (b)	Ufm requirement f	er Title
5 Sources : Plense	Teview and update the	facility
of ations and maintinance p	no to include the da	to and the
OF CHAIS STUDY OF BUTTONE (AUST of the Pmin -	
Corrective action taken as	well as the time the	emission.
CLASEM. DOCUMENT THIS INTOX	mation tocall booking -	
Funitive dust emission points.	such as the clinker sto	rage shed
Additionally, please keep 0	9m records on the foll	owing
The Raw Mil	L. the tire terelor and	the deal
mill as their operation con	tributes to emission r	eduction
Reg. I 9.15 (c) Please report	the corrective Action 1	take regarding
Please submit a written report within ten (2/3/99 by inspector 10) working days describing the	monitor /
corrective action you have taken or propose	to take, including a schedule, to a	address the
above deficiencies. Issued by:	Received by	2
	Signing this is not an admission of gr	HIt

"WESTERN REGION" April 26, 1999

Elizabeth Gilpin Puget Sound Air Pollution Control Agency 110 Union Street, Suite 500 Seattle WA 98101-2038

Dear Ms. Gilpin:

Re: Compliance Status Report Dated 02/05/99

The following is further information as you requested on fugitive dusting noted from our clinker shed penthouse.

February 3, 1999:

On February 3, fugitive dust was noted coming from the door of the penthouse on the Clinker Shed. That night, the door to the penthouse was cleaned and closed properly to better seal the penthouse. On February 5, the duct work for drafting the penthouse was inspected and found to be restricted due to built up material. This was cleaned to allow proper drafting.

Sincerely,

J. Trygve Grey **Process Engineer**

PUGET SOUND AIR POLLUTION CONTROL AGENCY

110 Union Street, Suite 500, Seattle, Washington 98101-2038

Registration No. 11339	Case No.
•	STATUS REPORT
Date of Report September 23	, 19 <u>98</u> atn
Source Name	Responsible Person, Title
Ash Grove Cement Co.	Henrik Voldback
3801 E. Marginal Way So	. Seattle, WA. 98134
respect to the areas of the facility I inspect our review of your July 199 During my inspection I noted the followin	
on July 18 1998.	ge from the main Stack
111 11 11 7600 0	en report. This determination interim CEM policy which by the board and which is
-	(10) working days describing the necessary se to take, including a schedule, to address the Received by Signing this is not an admission of guilt

PUGET SOUND AIR POLLUTION CONTROL AGENCY

110 Union Street, Suite 500, Seattle, Washington, 98101-2038 Fax 206-343-7522

Date of R	eport 10/16	
Source N		Responsible Person, Title
Ash	Grove Cement Co.	Henrik Voldback Mi
Location		
380	I E Marginal Way 50.	Seattle, Wa 98134
	violations of PSAPCA's regulations were opect to the areas of the facility I inspected.	bserved at the time of my inspection, with
_		
Du	ing my inspection I noted the following de	ficiencies:
2	August 1998 CEM TO	port no deficiencies
	the second secon	

PUGET SOUND AIR POLLUTION CONTROL AGENCY OCT 3 0 1998

110 Union Street, Suite 500, Seattle, Washington, 98101-2038
Fax 206-343-7522

SERT MAIL NO 2 580 038 810
Segistration No. 1/339

ANDLINE TENVITE

Case No.

COMPLIANCE STATUS REPORT

Date of	Keport Man 19 Report 10/23/58 Name Responsible Person	98	atm.	
Source	Name Responsible Person	on, Title		
As	sh Grove Cenent Co Henrik	Voldba	iek, PHMq	4
Location 380	ceattle, WA 98134			
50	eathe, WA 98134		** =	
	o violations of PSAPCA's regulations were observed at the tinespect to the areas of the facility I inspected.	ne of my insp	pection, with	
☐ Du	of May 1998 CEM report Juring my inspection I noted the following deficiencies: Office Reg The chion 12:03 (a) + (b): Omissing data for 50, + co month	ors for	7,45% of	
	for NOx montor for 25% of operating 22-23, and 28, 1998. Please pro	and 5	1/23/98 an	4 473
	explanation of how downtime man 12.03(b)(1), if appropriate. The Agric	meet k	esthe right h	to be fur the
		15/98 as		ang a
	as response included in CEM.		This dete	, A
	15 based on the 9/10/98 intour	CEM	alian which	h
	Chand .	- 15-SU	bject to	
	Please submit a written report within ten (10) working de corrective action you have taken or propose to take, includi above deficiencies.			
/Issued by		is not an adn	nission of guilt	



PUGET SOUND

AIR

POLLUTION

CONTROL

AGENCY

KING COUNTY

KITSAP COUNTY

PIERCE COUNTY

SNOHOMISH COUNTY

December 18, 1998

Registration No. 11339

Mr. Henrik Voldbaek Ash Grove Cement Co. 3801 E. Marginal Way S. Seattle, Washington 98134

Dear Mr. Voldbaek:

Disposition of Notice of Violation No. 36679

Based on the information you provided to us in your corrective action letter dated November 10, 1998, this Agency considers the above-referenced matter closed and will take no further enforcement action in this case.

If you have any questions concerning this matter, please contact me at 689-4078.

, //

Sincere

Neal J. Shulman Manager -Inspection

EMG:VJD

Dennis J. McLerran, Air Pollution Control Officer

"WESTERN REGION"

November 5, 1998

Ms. Melissa McAfee
Puget Sound Air Pollution Control Agency
110 Union Street, Suite 500
Seattle, WA. 98101-2038

Re: Compliance Status Report request for May 1998.

Dear Ms. McAfee:

The above requested an explanation on how monitor downtime in May 1998 might meet Regulation I Section 12.03 (b)(1). I am assuming the regulation you cite is found in the amended sections of Article 12 that became effective June 1, 1998. Although I am not sure that it is applicable, Section 12.03 (b)(1) exempts the data recovery requirement for periods of monitoring system downtime.

The May CEM report explains that all analyzer downtime for the month was related to a catastrophic failure of the Monitor Labs 8940 NOx analyzer. This failure effected the entire system since all three analyzers (NOx, SO2 and CO) share a common sample line. Isolating one analyzer to for maintenance requires the shutdown of the other two in the system.

Additionally, The May 1998 CEM report included a explanation and a maintenance history for the 8940 NOx analyzer to demonstrate proper maintenance was on going. PSAPCA was appraised at the time of the system failure and of the remedial efforts then underway.

I hope this explanation is sufficient but if you have additional questions, please advise.

Yours truly,

Gerald J. Brown

Mánager Safety and Environmental

Copy: HV

TG



PUGET SOUND

AIR I

POLLUTION

CONTROL

AGENCY

KING COUNTY

KITSAP COUNTY

PIERCE COUNTY

SNOHOMISH COUNTY

December 18, 1998

Registration No. 11339

Mr. Henrik Voldbaek Ash Grove Cement Co. 3801 E. Marginal Way S. Seattle, Washington 98134

Dear Mr. Voldbaek:

Disposition of May 1998 Compliance Status Report

Based on the information you provided to us in your corrective action letter dated November 5, 1998, this Agency considers the above-referenced matter closed and will take no further enforcement action in this case.

In the future, please examine the configuration of your sample line system for your CEMs to enable you to take one monitor off-line for maintenance and keep the other two on-line. This will provide a demonstration that the monitor down time was not a result of inadequate design per Regulation I, Section 12.03(b)(1).

If you have any questions concerning this matter, please contact me at 689-4078.

Sincerely,

Neal J. Shulman

Manager -Inspection

EMG:VJD

Dennis J. McLerran, Air Pollution Control Officer

BOARD OF DIRECTORS



"WESTERN REGION"

June 23, 1998

Ms. Melissa McAfee
Puget Sound Air Pollution Control Agency
110 Union Street, Suite 500
Seattle, WA. 98101-2038

Re: Notices of Violation No. 36713

Dear Ms. McAfee:

The above NOV requires a response describing the corrective to prevent a reoccurrence.

The Addendum to the March 1998 CEM report describes the SO2 event which was caused by a lack of lime in the main sorbent bin. To reduce the possibility of running out of sorbent, weight cells will be installed on the sorbent bin to increase inventory accuracy. This measurement will be read in the control room and allow for ongoing monitoring of available sorbent and the rate at which it is being used..

Installation of the weight cells will be accomplished in July and the system should be fully operational by the end of August 1998.

Please call me should you require additional information.

Yours truly

Gerald J. Brown

Manager Safety and Environment

cc: Henrik Voldbaek

PUGET SOUND AIR POLLUTION CONTROL AG 110 Union Street, Suite 500, Seattle, Washington 98101-2038

Fax: 206-343-7522

AGCW-SEATTLE

Redistration No. 11339	Case No.
COMPLIANCE	STATUS REPORT
Date of Report December 17	, 19 <u>98</u> atm.
Source Name A5H Grove Cement Co.	Responsible Person, Title Gerald Brown EHAS Mgr.
Location 3801 E Marginal Way So	o. Seattle, WA. 98134
respect to the areas of the facility I inspect of the Septem During my inspectional noted the following	
Pate Pollutant Poli 9/1 Reg I Opac Toli 9/1 Opacity	Regulation/ Permit Condition
10/4 9/4 opacity 10/4 9/4 opacity	Reg I 9.04 (c)(1) Reg I 9.04 (c)(2) Reg I 9.04 (c)(1)
10/30 9/30 NOX 10/30 9/30 NOX 10/30 9/14 Opacity	Reg 1 9.04 (c)(2) N/C 7381 5 (b) N/C 7381 5 (b) MISSIRA Data 2 to Reg I 1203(b)
U/R. 10/8 9/8 50, 10/2 10/0 502	Missin Data 4.5 hr. Reg I (2.03(b) 5 hr. 4.25 hr. 1 (10) working days describing the necessary
corrective action you have taken or propo	se to take, including a schedule, to address the trese determinations were based, on the o/98 EPA interim CEM civil penalty policy wich has not been board approved to which is

Received by

PSAPCA Form No. 70-182 (7/1/93) jrs

Signing this is not an admission of guilt

ARTICLE 9: EMISSION STANDARDS

SECTION 9.03 EMISSION OF AIR CONTAMINANT: VISUAL

STANDARD Adopted 03/13/68 (12)
Revised 07/08/70 (126), 04/11/73 (186), 06/09/88 (621) 05/11/89 (643), 09/08/94 (798), 04/09/98 (865)

- (a) It shall be unlawful for any person to cause or allow the emission of any air contaminant for a period or periods aggregating more than 3 minutes in any 1 hour, which is:
 - (1) Darker in shade than that designated as No. 1 (20% density) on the Ringelmann Chart, as published by the United States Bureau of Mines; or
 - (2) Of such opacity as to obscure an observer's view to a degree equal to or greater than does smoke described in Section 9.03(a)(1).
- (b) The density or opacity of an air contaminant shall be measured at the point of its emission, except when the point of emission cannot be readily observed, it may be measured at an observable point of the plume nearest the point of emission.
- (c) This section shall not apply when the presence of uncombined water is the only reason for the failure of the emission to meet the requirements of this section.
- (d) This section shall not apply to solid fuel burning devices, permitted fire training facilities, motor vehicles when operated on public roads, aircraft, or equipment subject to Section 9.04.
- (e) This section shall not apply to equipment with an alternate opacity standard issued under Section 3.03 or Section 6.07 that is based upon a correlation with the particulate concentration and that accurately indicates a violation of the applicable particulate emission standards in Section 9.09.

SECTION 9.04 OPACITY STANDARDS FOR EQUIPMENT WITH CONTINUOUS OPACITY MONITORING SYSTEMS Adopted 04/09/98 (865)

- (a) Applicability. This section shall apply to all equipment required to be equipped with a continuous emission monitoring system for opacity.
- (b) It shall be unlawful for any person to cause or allow the operation of any of the following equipment unless equipped with a continuous emission monitoring system for opacity:
 - (1) Cement kilns;

- (2) Clinker coolers;
- (3) Glass furnaces, rated at greater than 1 ton per hour, that burn fuel;
- (4) Fuel burning equipment, rated at 100 million Btu per hour or greater, that burns wood, coal, or residual oil; and
- (5) Refuse burning equipment rated at greater than 12 tons per day.
- (c) It shall be unlawful for any person to cause or allow the emission of any air contaminant from any equipment subject to this section during any hour that:
 - (1) Averages greater than 5% opacity; or
 - (2) Contains any consecutive 6-minute period averaging greater than 20% opacity.
- (d) Section 9.04(c)(1) shall not apply to:
 - (1) Glass furnaces that are tested annually for compliance with the applicable particulate emission standard in Section 9.09; or
 - (2) Equipment with an alternate opacity standard issued under Section 3.03 or Section 6.07 that is based upon a correlation with the particulate concentration and that accurately indicates a violation of the applicable particulate emission standards in Section 9.09.
- (e) This section shall not apply to sources controlled by a venturi scrubber, provided that:
 - (1) The source is tested annually for compliance with the applicable particulate emission standard in Section 9.09;
 - (2) The pressure drop across the scrubber is continuously monitored and recorded; and
 - (3) The scrubbing liquid flow rate and temperature are continuously monitored and recorded.
- (f) This section shall not apply to fuel burning equipment that burns residual oil less than 31 days per year, provided that the source implements an alternate opacity monitoring plan issued under Section 3.03 or Section 6.07.

SECTION 9.05 REFUSE BURNING Adopted 03/13/68 (12) Revised 06/09/88 (621), 12/09/93 (769)

(a) It shall be unlawful for any person to cause or allow the burning of combustible refuse except in a multiple chamber incinerator provided with control equipment.



"WESTERN REGION"

January 22, 1999

Elizabeth Gilpin Puget Sound Air Pollution Control Agency 110 Union Street, Suite 500 Seattle WA 98101-2038

Dear Ms. Gilpin:

Re: Compliance Status Report dated 12/17/98

The following is further information as you requested on the excess emissions reported in our CEM from September, 1998. Included is the information already supplied in the original CEM followed by the new information in Bold Face. We hope this is adequate.

NO_x Emissions:

		Hourly
Date	Time	Value
09/29/98	21:00	724 ppmc
09/29/98	22:00	979 ppmc
09/29/98	23:00	856 ppmc
09/30/98	00:00	783 ppmc
09/30/98	01:00	759 ppmc

We were unable to operate our coal mills and had to switch unexpectedly to full gas. This unplanned switch in fuels caused instability and high NO_X. It took the operator several hours to restabilize the kiln by making adjustments to the draft, feed rate and fuel rates. The coal mills were unable to operate because of electrical problems with the control system. An engineer and electrician were called out when the problem was noticed at 21:00. The coal mills were restarted at 01:40 and the main fuel source was gradually switched back to coal. This incident should be excused from penalty under WAC 173-400-107 (6). The event was not caused by poor operation, design or maintenance. As was shown above it was handled in a prompt manner. It is not of a recurring pattern as this in the first event in two years caused by problems with the coal mill control system.

An operator trained in the programming of Allen Bradley PLC's had made some changes in the existing automation program for our coal mills to dampen analog noise to the operator interface. After this, we began receiving erratic analog signals for control of the mills. The changes made by the operator should not have caused the apparent logic error. These changes are made on a routine basis by the process department. After these changes were entered, the original settings were not accepted by the PLC. Reloading an old copy of the program into the PLC solved the short term problem. For the long term solution, the operator was given restrictions of the type of changes he can make to the program.

Opacity:

		6-Minute	1-Hour
Date	Time	Average	Average
09/01/98	03:12	20.5 %	6.4 %
09/01/98	03:13	22.5 %	
09/01/98	03:14	23.9 %	

The kiln was in full operation including the baghouse. Through the initial investigation, it was discovered that compartment 10 was causing the problems. This was immediately isolated for repairs.

A complete change out of all the bags was performed and several cracks to the housing were found and repaired. This compartment had been inspected on 8/24. At that time, a small amount of dust was found on the floor, but no holes were found in either the bags or the housing. At that time, the compartment was cleaned and put back on line with no incident.

		6-Minute	1-Hour
Date	Time	Average	Average
09/04/98	12:02	21.2 %	5.8 %
09/04/98	12:03	22.9 %	
09/04/98	12:04	24.7 %	

The kiln was in full operation including the baghouse. Through the initial investigation, it was discovered that compartment 10 was causing the problems. During the previous two days, repairs had been done to compartment 10 including a complete bag changeout and repairs to the housing. It was still found to be leaking in the housing.

Additional cracks were found in the flooring and walls. These were repaired and after a complete inspection, the compartment was returned to service.

		6-Minute	1-Hour
Date	Time	Average	Average
09/05/98	01:44	20.5 %	8.1 %
09/05/98	02:00		8.8 %
09/05/98	03:00		12.4 %
09/05/98	04:00		8.2 %

The kiln was in full operation including the baghouse. Although working adequately under normal operation, there were still problems with compartment 10. The Raw Mill shut down at 01:40 causing a high differential pressure across the baghouse. At this time, compartment 10 was isolated and the kiln was reduced about 15% in production to help.

Upon inspection, it was found that additional cracks had developed in the housing of the compartment. These repairs were made and a complete inspection was made to the compartment after which it was put back on line. To prevent further a recurrence, a metal thickness gauge will be purchased or other measures will be taken to better monitor the thickness and condition of the floor and walls.

Sincerely,

J. Trygve Grey (Process Engineer